



GARY R. HERBERT  
Governor  
SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Minerals Inspection Report

Report Date: **04/23/2015**

Reviewed 

Mine Name: GR200 Plus	Permit Number: S/019/0066	Mine Status: Suspended
Operator Name: GR 200 Plus LLC	Inspection Date: 04/21/2015	Permit Fees: Delinquent
Inspector(s): M. Bradley	Inspection Time: 11:00am	Bond Amount: \$27,100
Attendee(s): Chris Dunham, Dennis Cosby, AGs	Weather: Clear, mild	Bond Escalation: 07/16/2015
Inspection Purpose: Follow up from enforcement		Prior Inspection: 08/25/2014

### Conclusions and Recommendations

Location: 572740.00 m E, 4308573.00 m N, UTM Zone 12N. Met to discuss reclamation options with property owner and miner. Conversation turned to possibility of repermitting the mine by the former contract miner. Inspection indicated not much change in the operation, other than the welding tanks had disappeared. Clarified for the miner that disturbed area included the footprints of the buildings and gravel piles, where he thought it only included the actual excavation.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Permit from GR 200 Plus LLC has been suspended. Disturbed area, including excavation, buildings, and footprints of gravel piles exceeds the 5 acres permitted and bonded (~19+ acres).			
2.	Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>
3.	Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4.	Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fuel tank on flatbed trailer requires secondary containment and is not in compliance with regulations			
5.	Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Reclamation required to bring acreage back to permitted area			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: A.G. Cooper and Associates;

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M019-Grand/S0190066-GR200Plus/inspections/INSP-04212015.pdf



Looking NW across disturbed area



Globemallow was prevalent over the site